



TYPICAL CONDITION
OF INTERIOR PARAPETS

SIGNIFICANT DISTRESS
AND THROUGH FLOOR
DISTRESS AT BOTTOM OF
CONCRETE BOX GIRDERS.
NOTE BOX IS OVER
LIVE TRAFFIC

TYPICAL EXTERIOR PARAPETS.
NOTE PARAPETS OVER LIVE TRAFFIC

TYPICAL CONDITION OF POST-TENSION
B-40-285-038C
Corrosion on Post Tensioning Anchorages

RIDING SURFACE WITH PATCHES
AND CONTINUED DISTRESS

HEAVILY CORRODED PILE
IN CELLULAR ABUTMENT

REPAIR AREAS UNDER BOX GIRDERS
WITH ADDITIONAL STRESS

